

WEST PENN WIRE

2833 West Chestnut Street
Washington, PA 15301
Toll Free: 800-245-4964
Fax: 724-222-6420
www.westpenn-wpw.com

CN-FS1BNC




24-7371P




TL-CSST



Fold Braid and Foil
over the Jacket



Carefully Place Center Conductor Into The
Pin Cavity Hole.



Carefully Slide the Center Conductor into
the Internal Center Hole. If you feel a slight
snag, rotate the cable and softly pump the conductor
into the connector.



Compress the connector onto the cable. **TL-SNSA** Tool is
an adjustable tool. You may have to adjust the tool for
complete compression.
Alternate Compression Tools: **TL-548G** or **TL-CPLCCTSLM**